MATERIAL SAFETY DATA SHEET FOR COATINGS, RESINS AND RELATED MATERIALS

Enamels 6 - 12M-10/90

MANUFACTURER: Tru-Test Manufacturing Company ADDRESS:

EMERGENCY MEDICAL INFO: 1-800-228-5635

(Formerly General Paint & Chemical Co.) TECHNICAL INFORMATION: 201 Jandus Road

1-708-639-5383

Cary, IL 60013

DATE OF PREPARATION: July 25, 1990

SECTION I - PRODUCT IDENTIFICATION

UX-1, 2, 6, 7, 11, 14, 17, 21, 23, 24, 31, 41, 42, 43, 46, 48 PRODUCT NUMBERS

PRODUCT NAME

Tru-Test Supreme HiQ Polyurethane Enamel

PRODUCT CLASS

Polyurethane Gloss Enamel

SECTION II - HAZARDOUS INGREDIENTS

INGREDIENT / CAS. NO.			OCCUPATIONAL	VAPOR
	***	KT_%	EXPOSURE LIMITS TLV PPM PEL	
Mineral Spirits *Diatomaceous Silica **Hydrous Magnesium Silicate	64742-47-8 68855-54-9 14807-96-6	34-45%	100ppm 500ppm	2.0
		4-9% 3-8%	10mg/m ³ 0.08mg/m	
			2mg/m^3 15mg/m^3	NA -

*This ingredient only in UX-17 & 31

(5) = This ingredient is subject to the reporting requirements of SEC. 313 SARA Title III

NA = Not applicable NE = Not established

SECTION III - PHYSICAL DATA

BOILING RANGE 300-380 OF VAPOR DENSITY XHEAVIER LIGHTER THAN AIR EVAPORATION RATE * FASTER X SLOWER THAN ETHER Volatile Organic Content (VOC) less than 380 gm/L

% VOLATILE VOLUME

*WT/GAL lbs

^{**}This ingredient only in UX-17

SECTION IV - PIRE AND EXPLOSION HAZARD DATA

FLAMMABILITY CLASSIFICATION OSHA Class II FLASH POINT 105°F LEL 0.9

DOT Combustible Liquid

EXTINGUISHING MEDIA: FOAM d'ALCOHOL'

d'ALCOHOL" X CO2

DRY CHEMICAL

WATER FOG

OTHE

UNUSUAL FIRE AND EXPLOSION HAZARDS - Closed containers may explode when exposed to extreme heat. Isolate from heat, sparks and open flame.

SPECIAL FIREFIGHTING PROCEDURES - Treat as a volatile liquid fire. Water spray may be ineffective. If water spray is used, fog nozzles are preferable.

SECTION V - HEALTH HAZARD DATA

EFFECTS OF OVEREXPOSURE - Severe eye irritation, drying of skin, excessive inhalation, causes headache, dizziness & nausea. Severe eye irritation, drying of skin, excessive inhalation, causes headache, dizziness & nausea. In the Diatomaceous Silica is Crystaline Silica (CS)which is considered a hazard by inhalation, IARC has classified CS as probably carcinogenic for humans (2A), from lab animal studies. CS has not been classified as a MEDICAL CONDITIONS PRONE TO AGGRAVATION BY EXPOSURE: Carcinogen by NPT or OSHA.

None known to General Paint & Chemical Co.

PRIMARY ROUTE(S) OF ENTRY:

★DERMAL

MINHALATION

DINGESTION

EMERGENCY AND FIRST AID PROCEDURES

Eyes & Skin: Wash with fresh water. Wash skin with warm water & soap.

Inhalation: Remove to fresh air. Apply artificial respiration if necessary. Get medical

Ingestion: Do not induce vomitting. Keep person warm and quiet. Get medical attention.

- SECTION VI - REACTIVITY DATA

STABILITY OUNSTABLE X STABLE

HAZARDOUS POLYMERIZATION DMAY OCCUR WILL NOT OCCUR HAZARDOUS DECOMPOSITION PRODUCTS

CONDITIONS TO AVOID

Isolate from heat & open fire.

INCOMPATIBILITY (MATERIALS TO AVOID)

Avoid contact with strong oxidizing agents

SECTION VII - SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Eliminate all ignition sources. Contain spill, absorb liquid with clay, sand or floor absorbent. Prevent run-off to sewers, streams or other bodies of water.

WASTE DISPOSAL METHOD

Contaminated absorbent may be deposited in a landfill in accordance with local, state and federal regulations.

SECTION VIII - SAFE HANDLING AND USE INFORMATION

RESPIRATORY PROTECTION - NIOSH/MSHA jointly approved air supplied respirator if TLV limits are exceeded. Approved mechanical filter to remove solid airborne particles of overspray during application.

VENTILATION - Provide sufficient mechanical (general and/or local exhause) ventilation to maintain exposure below TLV.

PROTECTIVE GLOVES - Required to prevent prolonged or repeated contact

EYE PROTECTION - Use of safety eyewear is recommended to prevent eye contact.

OTHER PROTECTIVE EQUIPMENT- Impervious clothing & boots are suggested to prevent PYGIENIC PRACTICES:

Wash hands before eating, smoking or using bathroom Do not reuse contaminated clothing.

SECTION IX - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING
Keep away from heat sparks and open flames. For storage conditions see OSHA 1910.106

OTHER PRECAUTIONS

Do not take internally. Avoid prolonged contact with skin. Containers should be grounded when pouring.

Avoid free fall of more than 2 - 3 inches when pouring.